

CASH MACHINE COMPANY

parts

CATALOGUE FOR

the

SPEEDTWIN

2

QUILTER

model

43AV-2




FOR THOSE WHO DEMAND THE BEST

*0...

100 OUTENRGCP, LOUISVILLE, KY 40214


(502)361-1726


FAX: (502) 381-4287





From the library of: Diamond Needle Corp

43AV-2











C-97648




103018



95024

190

0532
394646



COMPLETE
ASSEMBLY No. 97694



1560



1560




C-97002



C-97001



109316



97696



97798-3




82525



97698



97688



C-97806




C-0978




C-0976




C-97651




From the library of Diamond Needle Corp



37949
Solid Type
SOLID TYPE




3T3490
Split Type
SPLIT TYPE




103109



103108




103121




G-103014




103104




103015



97949
SOLID TYPE BOBBIN



979490
SPLIT TYPE BOBBIN



103109

50383

C704

C704

C705

C1475

C704

C704

C704


C704

C602

AFTER 8/79
SCS $\frac{1}{4}$ -28 x $\frac{3}{4}$
PRIOR 8/79
SCS $\frac{1}{4}$ 20 x $\frac{3}{4}$




C603






C603

AFTER
8/79
MOD 12L




C20-10


6




Complete Bobbiw Case:

14oLDCI2, Asscmbiv Pa♦t Muwbck.
c-iins






1. WHEN NEEDLE IS IN THE DOWN STROKE THE FRONT OF HOOK OPENING SHOULD BE AT THE REAR OF THE NEEDLE AS ILLUSTRATED.




2. WITH THE NEEDLE IN THE SAME POSITION AS BEFORE, ADJUST THE WEIGHT OF THE NEEDLE UNTIL THERE IS A BETWEEN THE BOTTOM PART OF NEEDLE EYE AND THE BOTTOM PART OF THE STEP OF THE INNER RACE.




Always Make Sure This Position.

3. ROTATE HEAD FORWARD UNTIL LEFT SIDE OF NEEDLE IS EVEN WITH THE POINT OF HOOK AS ILLUSTRATED.




TOP OF NEEDLE EYE SHOULD BE 1/16 BELOW POINT OF HOOK.





WITH NEEDLE IN SAME POSITION AS BEFORE THERE SHOULD BE NO CLEARANCE BETWEEN NEEDLE AND HOOK.

5. THERE SHOULD BE 1/32 CLEARANCE BETWEEN BOBBIN CASE RING AND BOBBIN RETAINER SPRING.




4. WITH NEEDLE IN THE DOWN STROKE THE NEEDLE DEFLECTOR SHOULD BE 1/16 AWAY FROM THE NEEDLE.






43270

SET SCREW
No. 449




97942




41897




97748



41446



41896



41899


176



97750




346



97749


896




41894

457

From the library of: Diamond Needle Corp







CM $\diamond$ o//r~

TIRJH





W






43 AV-2






C-0cL90j₅



Spar SruT pyusiy

■ "ILJ2d/i2jJs?".'BuiriiNisr

e:




From the library of: Diamond Needle Corp


ZZ\BQ-i,

S9HDD


SA-RB-14-




240 H B150-6



C-75550




C-75551





240 H 150

5 Av/-




From the library of: Diamond Needle Corp






S♦FtR To FoLOWIMC, pAGe

Foe Paets MuMe.Ei.iiSi





VBelt-513&0

(OR?) 5L380 -C 1963-1971


5m-to c wi-ivi

5L460 C 1971-1979

10528

32


932



BK-30

'93


932



CM- $\diamond$ a



($\diamond$ -Z209



T"vv\njvv\vuvi-avT/i/uuvi


PfiTrerJw 7/?«cK

rJwJEBTS OA(iY)

?att£pn T(?ficK






L.

43 AV-2



From the library of: Diamond Needle Corp


13 4v3 AV-2







Aiew Sr/tE. TASLt

NEW STYLE TABLE

from the library of: Diamond Needle Corp






From the library of: Diamond Needle Corp




43 AV-6

C-/a3/CD
C-10316H10D



<-2-ddiar-A2

C-2-802T-A2




802T-WIA%
ARM & ROLLER ONLY

<7 i-r

43 A V L


X-2 CoAPStjrojJ
i BQEV Atr V Lvc
3o3o Io4- DiAPMffM
C IIS" A3o Vane Switch

Or) MzST Co' Wfre




ri3~:


43 AV-6 & 43 AV-2




S//i/rrLE Dr/i/i Smpt
SHUTTLE DRIVE SHAFT
NO. - 4365-S



7E,
3
ImSF jDJiyi S//ift
LOWER DRIVE SHAFT
NO. - 4368-S



Cfst NS-AD 3672Z-
SirjCLS
HEAD 72"
SINGER HEAD 66 1/2"
//eAD D//ySS/AFT
HEAD DRIVE SHAFT
NO. - 4363-S



AiX//E-AD SM/T
/W-43i.Z"S
AUX. HEAD SHAFT TO COMPRESSOR
NO. - 4362-S

43 NV-C



JSSS-♦
98534




COD
103112
103112


103111
103111



5732S
97925



C-37323
C-97923



5844S
98449



34-S0
98450



T-1111